ROBIN AMERICA, INC.
WOOD DALE, ILLINOIS

SPECIFICATION FOR WISCONSIN ROBIN ENGINE

Application: CHARGE - RECOIL Specification No.: 800853

Model: W1-280 Date: 12/22/92 Pg. 1 of 1

For Production - same as parts list issue: 800417 with the following exceptions:

| CHG | LN# | ADD PART # | QTY | DESCRIPTION | OMIT PART # | SERVICE PART # |
|---|---|---|---|---|---|---|
| | 1 | EY2345154911 | 1 | AIR SHROUD | EY2345150101 | EY2345120107 |
| | 2 | EY0732003900 | 1 | LABEL (WARNING) | XXX | |
| | 3 | XXX | 1 | FUEL TANK | EY2346110201 | |
| | 4 | XXX | 1 | FUEL TANK CAP | EY0430430015 | |
| | 5 | XXX | 1 | FUEL FILTER | EY0641360010 | |
| | 6 | XXX | 1 | FUEL STRAINER | EY0642006400 | |
| | 7 | XXX | 2 | FLANGE NUT | EY0023808000 | |
| | 8 | EY0016508200 | 2 | BOLT | XXX | |
| | 9 | XXX | 1 | FUEL PIPE | EY2346260101 | |
| | 10 | EY2346239210 | 1 | CARBURETOR | EY2346239110 | |
| | 11 | EY2347012308 | 1 | FLYWHEEL | EY2347025001 | |
| | 12 | EY2347013008 | 1 | IGNITION COIL | EY2347022101 | |
| | 13 | EY2347013708 | 1 | LAMP COIL | XXX | |
| | 14 | EY0011706250 | 2 | BOLT & WASHER ASSY | XXX | |
| | 15 | EY0152060050 | 1 | TAPPING BOLT | XXX | |
| | 16 | EY2077500101 | 1 | CLAMP | XXX | |
| | 17 | | | | | |
| | 18 | | | | | |
| | 19 | | | | | |
| | 20 | | | | | |
| | 21 | | | | | |
| | 22 | | | | | |
| | 23 | | | | | |
| | 24 | SPECIAL NOTES: | | PAINT ENGINE SHEET METAL | | |
| | 25 | | | CANARY YELLOW # EY0901030410. | | |
| | 26 | | | | | |
| | 27 | | | | | |
| | 28 | | | | | |
| | 29 | | | | | |
| | 30 | | | | | |
| | 31 | | | | | |
| | 32 | | | | | |
| | 33 | | | | | |
| | 34 | | | | | |
| | 35 | | | | | |
| | 36 | | | | | |
| | 37 | | | | | |
| | 38 | | | | | |
| | 39 | | | | | |
| | 40 | | | | | |

| CHG | CHANGE NO./REFERENCE | DATE | CHG | CHANGE NO./REFERENCE | DATE |
|---|---|---|---|---|---|