Bill Bergeron

Subject: 263-71902-A1 30Amp Regulator (Before & After) 02-06-2019

Attachments: 2019_02_06_09_08_09.pdf; 263-71902-A1.jpg

From: Yoshitaka Tanabe <ytanabe@subarupower.com>

Sent: Wednesday, 06 February, 2019 9:18 AM

To: Rich Tranter <rtranter@subarupower.com>; Mark Failauga <mfailauga@subarupower.com>

Cc: Bill Bergeron
 Subject: 263-71902-A1 Regulator (Before & After)

So, you might continue hearing from the customers like, "hey, I got your regulator delivered, but it looks way different. Did you guys ship the right one?"

It is the replaceable with no problem. You can pass the attached if someone asked the detail.

In sum, the reason of changes are:

- ✓ Old spec's diecasting's die got so old, it's needed to replace.
- ✓ Taking that opportunity, they added more fins to improve the cooling performance.
- ✓ Also, per the supplier, they improved other electrical performance.

Sincerely,


Yoshi Tanabe | Operations Manager


Industrial Power Products of America, Inc. (Former Robin America, Inc.)

(DBA Subaru Industrial Power Products http://www.subarupower.com)

Address: 10801 88th Avenue, Pleasant Prairie, WI 53158 Phone: (847) 847-2952







This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. The integrity and security of this message cannot be guaranteed on the Internet.